

**Work Order ID 73108**

Thursday, August 25, 2011 4:03:46 PM



Page 1

Item ID: D205-778-011

Accept



Setup Start



Revision ID:

Stop



Item Name: Comfort Seat, LH/RH

Start Date: 8/26/2011 Start Qty: 1.00



Cust Item ID:

Required Date: 10/7/2011 Req'd Qty: 1.00



Customer:

Reference:

Approvals: Process Plan: CL Date: 11/08/26 Tooling: \_\_\_\_\_ Date: \_\_\_\_\_

QC: \_\_\_\_\_ Date: \_\_\_\_\_ SPC (Y/N): \_\_\_\_\_ Date: \_\_\_\_\_

Run Start



Stop



Sequence ID/ Work Center ID	Operation Description	Set Up/ Run Hours	Tool ID	Tool #	Plan Code	Accept Qty	Reject Qty	Reject Number	Insp. Stamp
--------------------------------	--------------------------	----------------------	---------	--------	--------------	---------------	---------------	------------------	----------------

Draw Nbr	Revision Nbr
D3800	B
DSI 9508	A
IIN D205-778	Rev B

100

0.00



DC

DOCUMENT CONTROL

Memo

0.00

Document Control

Photocopy bluefile &amp; type labels per PPP D205-778-011 CHG 003

8/19/11for ML 11-9-26 (1)

110

0.00



Packaging

Pick Kit

Memo

0.00

Packaging

11/9/26

W/O:		WORK ORDER CHANGES					
DATE	STEP	PROCEDURE CHANGE	By	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector

Part No: \_\_\_\_\_ PAR #: \_\_\_\_\_ Fault Category: \_\_\_\_\_ NCR: Yes No DQA: \_\_\_\_\_ Date: \_\_\_\_\_

Resolution: \_\_\_\_\_ Disposition: \_\_\_\_\_ QA: N/C Closed: \_\_\_\_\_ Date: \_\_\_\_\_

NCR:		WORK ORDER NON-CONFORMANCE (NCR)						
DATE	STEP	Description of NC Section A	Corrective Action Section B			Verification Section C	Approval Chief Eng	Approval QC Inspector
			Initial Chief Eng	Action Description Chief Eng	Sign & Date			

**NOTE:** Date & initial all entries

**Work Order ID 73108**

Thursday, August 25, 2011 4:03:46 PM

Page 2

Item ID: D205-778-011

Accept

Setup Start

Revision ID:

Stop

Item Name: Comfort Seat, LH/RH

Start Date: 8/26/2011 Start Qty: 1.00

Cust Item ID:

Required Date: 10/7/2011 Req'd Qty: 1.00

Customer:

Reference:

Run Start

Approvals: Process Plan: \_\_\_\_\_ Date: \_\_\_\_\_ Tooling: \_\_\_\_\_ Date: \_\_\_\_\_

Stop

QC: \_\_\_\_\_ Date: \_\_\_\_\_ SPC (Y/N): \_\_\_\_\_ Date: \_\_\_\_\_

Sequence ID/  
Work Center IDOperation  
DescriptionSet Up/  
Run Hours

Tool ID

Tool #

Plan  
CodeAccept  
QtyReject  
QtyReject  
NumberInsp.  
Stamp

120

QC4- 100% Inspect kits for completeness

0.00



QC

Memo

0.00

Quality Control

130

Packaging

0.00



Packaging

Memo

0.00

Packaging

Identify and pack for shipping as per PPP D205-778-101

Location: \_\_\_\_\_

PPP Rev: \_\_\_\_\_

140

QC21- Final Inspection - Work Order Release

0.00



QC

Memo

0.00

Quality Control

*Peapack**11/9/27**MF 11-09-27*

W/O:		WORK ORDER CHANGES					
DATE	STEP	PROCEDURE CHANGE	By	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector

Part No: \_\_\_\_\_ PAR #: \_\_\_\_\_ Fault Category: \_\_\_\_\_ NCR: Yes No DQA: \_\_\_\_\_ Date: \_\_\_\_\_

Resolution: \_\_\_\_\_ Disposition: \_\_\_\_\_ QA: N/C Closed: \_\_\_\_\_ Date: \_\_\_\_\_

NCR:		WORK ORDER NON-CONFORMANCE (NCR)						
DATE	STEP	Description of NC Section A	Corrective Action Section B			Verification Section C	Approval Chief Eng	Approval QC Inspector
			Initial Chief Eng	Action Description Chief Eng	Sign & Date			

**NOTE:** Date & initial all entries

Thursday, August 25, 2011 4:03:43 PM

Page 1

1. The first step in the process is to identify the problem or issue that needs to be addressed. This involves gathering information and understanding the context of the problem.

2. Once the problem is identified, the next step is to define the objectives and goals of the project. This helps to clarify what needs to be achieved and provides a clear direction for the team.

3. The third step is to develop a plan or strategy to address the problem. This involves breaking down the problem into smaller, manageable tasks and determining the resources needed to complete each task.

4. The fourth step is to implement the plan. This involves putting the strategy into action and monitoring progress regularly to ensure that the project is on track.

5. The final step is to evaluate the results of the project. This involves assessing the outcomes against the objectives and goals and identifying any areas for improvement.



**Required Date:** 10/7/2011

**Required Qty: 1.00**

IPP Rev:B as

\_\_\_\_\_

W/O:		WORK ORDER CHANGES					
DATE	STEP	PROCEDURE CHANGE	By	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector

Part No: \_\_\_\_\_ PAR #: \_\_\_\_\_ Fault Category: \_\_\_\_\_ NCR: Yes No DQA: \_\_\_\_\_ Date: \_\_\_\_\_

Resolution: \_\_\_\_\_ Disposition: \_\_\_\_\_ QA: N/C Closed: \_\_\_\_\_ Date: \_\_\_\_\_

NCR:		WORK ORDER NON-CONFORMANCE (NCR)						
DATE	STEP	Description of NC Section A	Corrective Action Section B			Verification Section C	Approval Chief Eng	Approval QC Inspector
			Initial Chief Eng	Action Description Chief Eng	Sign & Date			

**NOTE:** Date & initial all entries

# Picklist Print

Thursday, August 25, 2011 4:03:43 PM

Page 2

Work Order ID: 73108

Parent Item: D205-778-011

Parent Item Name: Comfort Seat, LH/RH

Start Date: 8/26/2011

Required Date: 10/7/2011

Start Qty: 1.00

Required Qty: 1.00

D3756-041  
Cushion

Manufactured No

110 Each

6.0000

1

Location

Loc Qty

Loc Code

ST252A

6

68935

2

71184

4

D3758-041  
Clamp

Manufactured No

110 Each

9.0000

2

Location

Loc Qty

Loc Code

ST081

9

58262

9

D3777-041  
Clamp

Manufactured No

110 Each

6.0000

2

Location

Loc Qty

Loc Code

ST081

6

46659

6

D3800-3-200  
Hook and Loop Strip (2" Hard)

Manufactured No

110 f

128.9000

2

Location

Loc Qty

Loc Code

ST083

128.9

56393

68.9

60044

60

1- Cut to length as per dwg (4x 6.00")

Thursday, August 25, 2011 4:03:44 PM

Shop Packet Print

Page 2

W/O:		WORK ORDER CHANGES					
DATE	STEP	PROCEDURE CHANGE	By	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector

Part No: \_\_\_\_\_ PAR #: \_\_\_\_\_ Fault Category: \_\_\_\_\_ NCR: Yes No DQA: \_\_\_\_\_ Date: \_\_\_\_\_

Resolution: \_\_\_\_\_ Disposition: \_\_\_\_\_ QA: N/C Closed: \_\_\_\_\_ Date: \_\_\_\_\_

NCR:		WORK ORDER NON-CONFORMANCE (NCR)						
DATE	STEP	Description of NC Section A	Corrective Action Section B			Verification Section C	Approval Chief Eng	Approval QC Inspector
			Initial Chief Eng	Action Description Chief Eng	Sign & Date			

**NOTE:** Date & initial all entries



# Picklist Print

Thursday, August 25, 2011 4:03:44 PM

Page 3

Work Order ID: 73108

Parent Item: D205-778-011

Parent Item Name: Comfort Seat, LH/RH

Start Date: 8/26/2011

Required Date: 10/7/2011

Start Qty: 1.00

Required Qty: 1.00

AN525-10R8

Purchased

No

110

Each

69.0000

8



Screw

Location

Loc Qty

Loc Code

ST325

69

114494

69

AN970-3

Purchased

No

110

Each

78.0000

8



Washers

Location

Loc Qty

Loc Code

ST349

78

115158

2

117395

76

AN960JD10

NAS1149D0363J

Purchased

No

110

Each

0.0000

8



Washer

MS21042L3

Purchased

No

100

Each

1,783.000

8



Nut

Location

Loc Qty

Loc Code

ST300

1783

117441

150

117601

400

117885

233

118451

1000

Thursday, August 25, 2011 4:03:44 PM

Shop Packet Print

Page 3

W/O:		WORK ORDER CHANGES					
DATE	STEP	PROCEDURE CHANGE	By	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector

Part No: \_\_\_\_\_ PAR #: \_\_\_\_\_ Fault Category: \_\_\_\_\_ NCR: Yes No DQA: \_\_\_\_\_ Date: \_\_\_\_\_

Resolution: \_\_\_\_\_ Disposition: \_\_\_\_\_ QA: N/C Closed: \_\_\_\_\_ Date: \_\_\_\_\_

NCR:		WORK ORDER NON-CONFORMANCE (NCR)						
DATE	STEP	Description of NC Section A	Corrective Action Section B			Verification Section C	Approval Chief Eng	Approval QC Inspector
			Initial Chief Eng	Action Description Chief Eng	Sign & Date			

**NOTE:** Date & initial all entries

#### 4.0 WEIGHT AND BALANCE

The following is the net weight increase associated with the modification kits.

Installation	Weight	LATERAL		LONGITUDINAL	
		Arm	Moment	Arm	Moment
<b>D205-778-011</b>	13.0 lb	±22.0 in	±286 in-lb	47.0 in	611 in-lb
Comfort Seat Kit, LH / RH	5.9 kg	±0.56 m	±3.3 m-kg	1.19 m	7.0 m-kg

#### 5.0 PARTS LIST

Qty -011	Part Number	Description
X	D205-778-011	COMFORT SEAT KIT (FITS LH & RH)
1	D3752-1	SEAT FRAME
1	D3755-041	CUSHION
1	D3756-041	CUSHION
2	D3758-041	CLAMP ASSEMBLY
*2	D3758-1	CLAMP
*2	D2182B028	RUBBER CUSHION
2	D3777-041	CLAMP ASSEMBLY
*2	D3777-1	CLAMP
*2	D2182B013	RUBBER CUSHION
4	D3800-3-200-060	HOOK STRIP
8	AN525-10R8	SCREW
8	AN970-3	WASHER
8	AN960JD10	WASHER
8	MS21042L3	NUT (OR MS21042-3)

\* REFERENCE ONLY. PARTS ARE INCLUDED IN ASSEMBLY ABOVE.

# DART SERVICE INSTRUCTION

TO AMEND INSTALLATION INSTRUCTIONS IIN-D205-778 REV. B  
AND INSTRUCTIONS FOR CONTINUED AIRWORTHINESS ICA-D205-778 REV. 1

REF TCCA STC: SH08-37  
REF FAA STC: SR02704NY  
REF EASA STC: EASA.IM.R.S.01518

REFERENCE ONLY

## PURPOSE:

To provide instructions to allow the hook strip (ie. velcro) on the D3752-1 Seat Frame to be fastened with rivets.

## CHANGE:

D205-778-011 Comfort Seat Kits at CHG 002 have rivets and washers that may be installed to fully secure the D3800-3-200-060 Hook Strip to the D3752-1 Seat Frame. The parts list of Installation Instructions IIN-D205-778 and Instructions for Continued Airworthiness ICA-D205-778 is amended as shown below. Installation of the rivets is optional.

## PARTS LIST

QTY -011	Part Number	Description
X	D205-778-011	Comfort Seat Kit
8	BSP-42	Rivet (Add)
16	NAS1149DN616J	Washer (or AN960JD6L) (Add)

## INSTALLATION INSTRUCTIONS

Install the BSP-42 rivets as detailed below, see Figure 1 of this service instruction as reference:

- 1) Ensure location of D3800-3-200-060 Hook Strip lines up with loop strip on seat cushions.
- 2) Drill D3752-1 Seat Frame using 9/64" (Ø0.141) drill in appropriate locations: ensure rivet location will not interfere (contact) with the OEM metal seat frame. Deburr hole.
- 3) Install each BSP-42 rivet with qty(2) NAS1149DN616J washers (one on either side of the plastic seat frame). It is acceptable to substitute longer/shorter BSP rivets or thicker NAS1149DN632J washers to ensure proper fit.

## UPGRADE KIT

For D205-778-011 Comfort Seat Kits at CHG 001, the DSI-9508-011 Rivet Kit is available from Dart:

QTY -011	Part Number	Description
X	DSI-9508-011	Rivet Kit
8	BSP-42	Rivet
16	NAS1149DN616J	Washer (or AN960JD6L)

CANADA  
DEPARTMENT OF TRANSPORT  
AIRCRAFT CERTIFICATION  
BRANCH  
DAO # 01-O-01

APPROVED

BY:   
D. SHEPHERD (DE # 02)

DATE: 10.03.02  
CERT. NO.: SH08-37  
ISSUE NO.: 1

A	NEW ISSUE	CP	10.03.02
REV.	DESCRIPTION	BY	DATE
DESIGN	qp	DART AEROSPACE LTD	
DRAWN	qp	HAWKESBURY, ONTARIO, CANADA	
CHECKED	AB	DRAWING NO.	REV. A
MFG. APPR.	N/A	DSI 9508	SHEET 1 OF 2
APPROVED	SH	TITLE	SCALE
DE APPR.	AA	RIVET KIT	NTS
DATE	10.03.02	COPYRIGHT © 2010 BY DART AEROSPACE LTD THIS DOCUMENT IS PRIVATE AND CONFIDENTIAL AND IS SUPPLIED ON THE EXPRESS CONDITION THAT IT IS NOT TO BE USED FOR ANY PURPOSE OR COPIED OR COMMUNICATED TO ANY OTHER PERSON WITHOUT WRITTEN PERMISSION FROM DART AEROSPACE LTD.	